



www.abreezo.com  
toll free: 800-461-0006

Jan 26 2010

## 2010 product update new bath fan improvements

In our continued efforts to improve the performance and quality of the ABREEZO bath exhaust fans, we have made the following changes:

### 1 - INCREASED AIRFLOW, QUIETER OPERATION


Abreezo is reintroducing the weighted back draft damper which is recessed inside the fan body collar. The weighted damper will provide less resistance during fan operation offering a more fluent air flow and quieter operation.



exhaust duct collar  
weighted backdraft damper recessed in duct collar

### 2 - HIGHER PERFORMANCE ELECTRONICS

After extensive testing, we have selected an upgraded electrical capacitor to ensure optimum performance for frequent on/off cycles. The connections at the capacitors have also been upgraded to ensure the wire connections do not come loose during installation.



upgraded capacitor and wiring inside easy-to-remove harness and quick-release Molex connector from power supply



www.abreezo.com  
toll free: 800-461-0006

page 1 of 2

Questions or comments about  
Abreezo?

e-mail: [contact@abreezo.com](mailto:contact@abreezo.com)  
phone: 800-461-0006



www.abreezo.com  
toll free: 800-461-0006

Jan 26 2010

# 2010 product update

## new bath fan improvements

### 3 - LONGER MOTOR LIFE

The Molex connector between the motor and power supply wiring harness will now be disconnected at the factory prior to shipping. This will ensure the fan is not energized during the construction phase while the debris protection board is still in place over the fan's intake. We have found that fans energized while the protective cardboard was still in place put an extreme load on the motor and this contributed to premature motor failure.

### 4 - NEW USER FRIENDLY PACKAGING


A new message has been put on the protective cardboard insert instructing the contractor to remove the cardboard and connect the Molex connector prior to placing the grill on the fan when construction and painting are complete.



protective cardboard insert keeps debris out of the fan during construction

### 5 - EASIER TO SERVICE

We have increased the length of the wires in the wiring harness. This will ensure a quick and easy change-out of the wiring harness and capacitor if the fan needs to be serviced.



longer wires make the wiring harness easier to work with



## Questions or comments about Abreezo?

www.abreezo.com  
toll free: 800-461-0006

page 2 of 2

e-mail: [contact@abreezo.com](mailto:contact@abreezo.com)  
phone: 800-461-0006